

**ABSTRACT**

A large ingot is produced by casting the zirconium alloy, then the ingot is forged in two stages to obtain the semi-finished product wherein the first stage of forging the  
5 ingot is performed at a temperature at which the zirconium alloy is in a state comprising crystalline  $\alpha$  and  $\beta$  phases.